

## TEST REPORT

Report No. : HL10266B/2024

Page : 1 of 3

Date : FEB. 05, 2024

### NULLPIXEL CO., LTD.

4F., No. 19, Ln. 1, Minfu St., Guishan Dist., Taoyuan City 333 , Taiwan (R.O.C.)

### The following merchandise was submitted and identified by the applicant as:

Product Description: W3.8 Rope

### We have tested the submitted sample(s) as requested and the following results were obtained:


Test Requested: Pulling test

Test Method & Result: --- See following page ---

Date of Receipt: Jan. 23, 2024

Testing Period: Jan. 23, 2024 ~ Jan. 30, 2024

Signed for and on behalf of  
SGS Taiwan Ltd.

  
Brian Huang  
Supervisor



## TEST REPORT

**Test Method:**

- (a). Secure the sample on the testing machine.
- (b). Apply an increasing upward force to the sample until it is damaged or slipped.
- (c). Record the max. force and any findings.
- (d). Testing Machine: INSTRON 5581, Rate: 30 mm/min.

**Test Result:**

Sample	Max. force (kgf)	Result
W3.8 Rope	1200	The metal adjustment buckle was damaged after testing.

Note: The content of this report is invalid if it is not presented as the entire report.

– Picture(s)–




Photo A: Appearance of the sample

Photo B: Test setup

## TEST REPORT

Report No. : HL10266B/2024

Page : 3 of 3

– Picture(s)–




Photo C: After testing




Photo D: Test curve

--- End of Report ---